

broken off and the key taken from the small pinion so that the switch could be opened without turning the arrow. The engineer seeing arrow in its correct position suspected nothing until the engine